



# Price Computing Scale

## Operation Manual


### 6. Change

6.1 In the above case, if customer pay 10.0 US dollar, press the key , then input 10.0 directly. The total price window will show "2.50" which means the Money should give back to customer.


6.2 Press the key  again to back to the price computing mode.

The above three accumulation will save in the memory unless you press the key  to clear memory.

### 7. Clear the memory

Press the key  to clear all the results in the memory.

### 8. Backlight switch

The backlight can be selected to be opened or closed by pressing the key . If the backlight is on, the backlight will auto off while there is nothing operation over 10 seconds. But the backlight will auto on while you do operation again.


### 9. Alarm sign

While the '-----' will be indicated in the weight window, which means overload this moment.

### 10. Recharge

10.1 Please recharging the scale over 8 hours at the first time before you use it. It is better to recharge under the state of shutdown.

10.2 When the battery electric quantity shows low battery, please plug in the scale to recharging.




#### Specification:

Capacity	3kg	6kg	15kg	30kg
Division	1g	2g	2/5g	10/5g
Pan size	285mm×240mm			
Power source	AC:110/220V DC:4V/4Ah			

## 1. Start the scale

1.1 Adjust the feet of scale ( has four feets on the bottom).

1.2 Press the key  , the scale will return to zero in 3 seconds . Then finish the start.


1.3 To make sure if the scale shows zero.If not, press the key  to return to zero. Please confirm that it indicates zero before weighting.

1.4 Please warm the scale for 10 minutes before operation in order to make more accurate.

## 2. Price computing

2.1 Place the goods on the pan, the weight window will show the weight of goods.

2.2 Price computing --- Input the unit price of goods by numerical keys. For example, the unit price of orange is US\$2.0 per kilogram. After input 2.0,the total price window will show total price.

2.3 If input the wrong figure, please press the key  to delete the wrong set and to input the correct figure again.

## 3. Tare

3.1 Place the outer package of goods on the pan and press the Key .

3.2 Move away the package, then place the goods with package on the pan.


3.3 The weight window will show the net weight of goods after the scale is stable.


## 4. Accumulation


If the goods wanted by customer are more than one ,you may press the key  to get the total price of all the goods.

For example, the unit price of apple and banana are US\$2.0/kg , US\$4.0 /kg respectively. If customer wants each




fruit one kilogram respectively, please operate the following steps.

4.1 After placing 1kg apple on the pan,you may input the unit Price 2.0 by numerical key , Then press the key  . The weight window will show “-Add-” and the unit price window will show “1” which means the first accumulation.

4.2 Move away the apple from the pan , and place 1kg banana on the pan. Input the unit price 4.0 by Pressing the numerical key while scale is stable. Then press the key  . The weight window will show “-Add-” and the unit price window will show “2” which means the second accumulation.

4.3 Press the key  again, the weight window will show “tARE”, unit price window will indicate “2” and total price window will show “6.00” which means the total price is 6.00.

## 5. Add

If your customer want to buy the other goods which price has been known after you have finished the above accumulation, you can use this key  to add that price. For example, your customer want to buy a bottle of orange juice which price is 1.5 USD/PC. In the above case, you may input the price 1.5 by numerical key, then press the key  . (At this moment, the weight window shows “-Add-”,the unit price window shows “3”, and the total price window shows “1.50”. Two seconds later, the unit price window shows “1.50”, the other windows show “0.00”.) Then press the key  to add 1.50 to 6.00. The unit price window indicates “3” and total window indicates “7.5” which means the total price is 7.5 USD.